

SAFETY RECALL

Infantino SlingRider

Model 141-210 UPC 773554512106

Model 151-210 UPC 773554512106

Model 151-528 UPC 773554515282

Model 151-534 UPC 773554515343

The plastic slider on the fabric strap can break. This can cause the strap supporting the carrier to release and infants to fall out of the carrier.



The recalled carrier has a sewn-in label marked “Made in China” and was sold from July 24, 2006 through February 2007.

Products labeled “Made in Thailand” or “New 2007 Design” are not affected by this recall.

Consumers should immediately stop using the carrier and return it to Infantino to receive a free replacement product.

Call Infantino toll free at **(888) 808-3111** between 8:00 a.m. and 4:00 p.m. PT Monday through Friday or visit <http://service.infantino.com> for more information.